

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,234,890 B1
APPLICATION NO. : 09/942112
DATED : June 26, 2007
INVENTOR(S) : Thomas Marshall et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1:

Line 21, it reads "The bullet receives bullets fired..."; should read --The bullet trap receives bullets fired...--
Line 26, it reads "...formed by a flat strip of steel 10 is used for the..."; should read --...formed using a flat strip of steel 10 on the...--
Line 28, it reads "12 welded to the back..."; should read --22 welded (indicated at 12) to the back...--
Line 32, it reads "...or leg 18 pinch two..."; should read --...or leg pinch two....--
Line 34, it reads "...or leg 18 are disposed..."; should read --...or leg are disposed....--
Lines 39 and 40, it reads "...thereby allowed the welded bolts break off."; should read --...thereby allowing the welded bolts to break off.--
Line 59, it reads "The above and other object..."; should read --The above and other objects....--

Column 2:

Line 17, it reads "invention, the a flat facing..."; should read --invention, a flat facing....--
Line 45, it reads "FIG. 6B shows and end view..."; should read --FIG. 6B shows an end view...--
Line 51, it reads "FIG. 7B shows and end view..."; should read --FIG. 7B shows an end view...--

Column 3:

Line 17, it reads "...the bend provides and angle..."; should read ----the bend provides an angle...--
Line 23, it reads "...pass through opening between..."; should read ----pass through an opening between....--
Line 33, it reads "...facing strip 34. This is"; should read --...facing strip 34. This is in--

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,234,890 B1
APPLICATION NO. : 09/942112
DATED : June 26, 2007
INVENTOR(S) : Thomas Marshall et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4:

Line 1, it reads "...relative to the bolts 42 so that"; should read --...relative to the bolts 42 (FIG. 3) so that--

Line 4, it reads "...the washer 46 or backing plate."; should readthe washer 46 (FIG. 3) or backing plate.--

Line 12, it reads "...because the facing 3 strip 68..."; should read --...because the facing strip 68...--

Signed and Sealed this

Tenth Day of February, 2009



JOHN DOLL
Acting Director of the United States Patent and Trademark Office